



Sun™ Dual FastEthernet/SCSI 6U CompactPCI Adapter With PMC Product Notes

Sun Microsystems, Inc.
901 San Antonio Road
Palo Alto, CA 94303-4900 U.S.A.
650-960-1300

Part No. 806-6043-12
August 2001, Revision A

Send comments about this document to: docfeedback@sun.com

Copyright 2001 Sun Microsystems, Inc., 901 San Antonio Road, Palo Alto, CA 94303-4900 U.S.A. All rights reserved.

This product or document is distributed under licenses restricting its use, copying, distribution, and decompilation. No part of this product or document may be reproduced in any form by any means without prior written authorization of Sun and its licensors, if any. Third-party software, including font technology, is copyrighted and licensed from Sun suppliers.

Parts of the product may be derived from Berkeley BSD systems, licensed from the University of California. UNIX is a registered trademark in the U.S. and other countries, exclusively licensed through X/Open Company, Ltd.

Sun, Sun Microsystems, the Sun logo, AnswerBook2, docs.sun.com, SunSolve Online, Sun Quad FastEthernet, and Solaris are trademarks, registered trademarks, or service marks of Sun Microsystems, Inc. in the U.S. and other countries. All SPARC trademarks are used under license and are trademarks or registered trademarks of SPARC International, Inc. in the U.S. and other countries. Products bearing SPARC trademarks are based upon an architecture developed by Sun Microsystems, Inc.

The OPEN LOOK and Sun™ Graphical User Interface was developed by Sun Microsystems, Inc. for its users and licensees. Sun acknowledges the pioneering efforts of Xerox in researching and developing the concept of visual or graphical user interfaces for the computer industry. Sun holds a non-exclusive license from Xerox to the Xerox Graphical User Interface, which license also covers Sun's licensees who implement OPEN LOOK GUIs and otherwise comply with Sun's written license agreements.

Federal Acquisitions: Commercial Software—Government Users Subject to Standard License Terms and Conditions.

DOCUMENTATION IS PROVIDED "AS IS" AND ALL EXPRESS OR IMPLIED CONDITIONS, REPRESENTATIONS AND WARRANTIES, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE OR NON-INFRINGEMENT, ARE DISCLAIMED, EXCEPT TO THE EXTENT THAT SUCH DISCLAIMERS ARE HELD TO BE LEGALLY INVALID.

Copyright 2001 Sun Microsystems, Inc., 901 San Antonio Road, Palo Alto, CA 94303-4900 Etats-Unis. Tous droits réservés.

Ce produit ou document est distribué avec des licences qui en restreignent l'utilisation, la copie, la distribution, et la décompilation. Aucune partie de ce produit ou document ne peut être reproduite sous aucune forme, par quelque moyen que ce soit, sans l'autorisation préalable et écrite de Sun et de ses bailleurs de licence, s'il y en a. Le logiciel détenu par des tiers, et qui comprend la technologie relative aux polices de caractères, est protégé par un copyright et licencié par des fournisseurs de Sun.

Des parties de ce produit pourront être dérivées des systèmes Berkeley BSD licenciés par l'Université de Californie. UNIX est une marque déposée aux Etats-Unis et dans d'autres pays et licenciée exclusivement par X/Open Company, Ltd.

Sun, Sun Microsystems, le logo Sun, AnswerBook2, docs.sun.com, SunSolve Online, Sun Quad FastEthernet, et Solaris sont des marques de fabrique ou des marques déposées, ou marques de service, de Sun Microsystems, Inc. aux Etats-Unis et dans d'autres pays. Toutes les marques SPARC sont utilisées sous licence et sont des marques de fabrique ou des marques déposées de SPARC International, Inc. aux Etats-Unis et dans d'autres pays. Les produits portant les marques SPARC sont basés sur une architecture développée par Sun Microsystems, Inc. L'interface d'utilisation graphique OPEN LOOK et Sun™ a été développée par Sun Microsystems, Inc. pour ses utilisateurs et licenciés. Sun reconnaît les efforts de pionniers de Xerox pour la recherche et le développement du concept des interfaces d'utilisation visuelle ou graphique pour l'industrie de l'informatique. Sun détient une licence non exclusive de Xerox sur l'interface d'utilisation graphique Xerox, cette licence couvrant également les licenciés de Sun qui mettent en place l'interface d'utilisation graphique OPEN LOOK et qui en outre se conforment aux licences écrites de Sun.

LA DOCUMENTATION EST FOURNIE "EN L'ETAT" ET TOUTES AUTRES CONDITIONS, DECLARATIONS ET GARANTIES EXPRESSES OU TACITES SONT FORMELLEMENT EXCLUES, DANS LA MESURE AUTORISEE PAR LA LOI APPLICABLE, Y COMPRIS NOTAMMENT TOUTE GARANTIE IMPLICITE RELATIVE A LA QUALITE MARCHANDE, A L'APTITUDE A UNE UTILISATION PARTICULIERE OU A L'ABSENCE DE CONTREFAÇON.



Sun Dual FastEthernet/SCSI 6U CompactPCI Adapter With PMC Product Notes

This document gives late-breaking information for the Sun™ Dual FastEthernet/SCSI 6U CompactPCI adapter with PMC.

Note – This version of the product notes refers to the adapter part numbers X6752A and X1339A.

Removing SCSI Devices From the Adapter

If you are using the Solaris™ 8 6/00 operating environment, you must install a patch before you can remove SCSI devices from the adapter.

Contact your Sun service representative to obtain the Solaris patch for this bug (patch ID number 108528-03 and future revisions).

After installing the patch, follow the instructions for connecting SCSI devices in the *Sun Dual FastEthernet/SCSI 6U CompactPCI Adapter With PMC Installation and User's Guide* (806-6042).

Note – If you are using the Solaris 8 10/00 operating environment, you do not need this patch.

QFE Driver Patch

The Sun Quad FastEthernet™ (`qfe`) device driver was designed for adapters with four Ethernet interfaces. You must install a Solaris patch before the Solaris software will recognize the Sun Dual FastEthernet/SCSI 6U CompactPCI adapter with PMC's two `qfe` interfaces.

This patch applies to both the Solaris 8 6/00 and Solaris 8 10/00 operating environments. Contact your Sun service representative to obtain the Solaris patch for this bug (patch ID number 108528-04 and future revisions).

`qfe.conf` File

Currently, `qfe.conf` file parameters are not used by the driver during hot swap. You must install a Solaris patch so that the `qfe.conf` file will be recognized during hot swap and after reboot. Once this patch is installed, you can use the `qfe.conf` file to set `qfe` device driver parameters.

This patch applies to the Solaris 8 6/00 and the Solaris 8 10/00 operating environments. Contact your Sun service representative to obtain the Solaris patch for this bug (patch ID number 108528-05 and future revisions).

Until the patch is released, use the `ndd` utility as specified in the *Sun Dual FastEthernet/SCSI 6U CompactPCI Adapter With PMC Installation and User's Guide* (806-6042) to set `qfe` device driver parameters.

PCI Mezzanine Cards

Sun does not currently provide PCI mezzanine cards (PMCs) with the Sun Dual FastEthernet/SCSI 6U CompactPCI adapter with PMC.

Contact your Sun service representative for more information about how to choose a PMC that is compatible with the adapter.

Full Hot-Swap

If your system has been set to full hot-swap mode, you must use the following procedure when installing the adapter (refer to your server documentation to determine if your server is set to full hot-swap mode):

1. **Install the adapter as specified in *Sun Dual FastEthernet/SCSI 6U CompactPCI Adapter With PMC Installation and User's Guide (806-6042)*.**
2. **Locate the hot-swap LED on the front card.**




FIGURE 1 Location of the Hot-Swap LED on the Front Card

3. **If the hot-swap LED is OFF (unlit), the I/O slots in the server are set to full hot-swap, and the adapter is activated.**



Caution – Make sure to complete Step 4. This is a workaround for a Solaris bug that will cause the system to hang.

4. Use the `cfgadm -al` command to verify that the adapter is attached to the server.

For more information on using the `cfgadm` command, refer to *Sun Dual FastEthernet/SCSI 6U CompactPCI Adapter With PMC Installation and User's Guide* (806-6042) and the `cfgadm` (1M) man page.

Improving qfe Interface Performance

To improve the performance of the adapter's `qfe` interface:

1. Add the following line to the `/etc/system` file:

```
set db21554:s_cache_line_size = 0x10
```

2. Reboot the system.

Refer to the Sun bug ID number 4380262 for more information on this `qfe` performance issue.

Screwdriver Needed for Installation

The "Installing the Adapter" chapter of the *Sun Dual FastEthernet/SCSI 6U CompactPCI Adapter With PMC Installation and User's Guide* (806-6042) has been updated.

The first bullet in the "Tools and Equipment" section reads:

- You will need a No. 0 Phillips screwdriver.

The correct information is:

- You will need a No. 2 Phillips or a small flathead screwdriver.

Rear-Access Adapter Part Number

The “Declaration of Conformity” section of the *Sun Dual FastEthernet/SCSI 6U CompactPCI Adapter With PMC Installation and User’s Guide* (806-6042) has been updated.

The product name reads:

Sun Dual Fast Ethernet/SCSI 6U CPCI Adapter with PMC (X1332A & X1339A)

The correct information is:

Sun Dual Fast Ethernet/SCSI 6U CPCI Adapter with PMC (X6752A & X1339A)

Midplane Connectors

The adapter midplane connectors conform to the PICMG 2.0 R3.0 specification.

Ethernet Port Pin Descriptions

The RJ-45 Ethernet connector pin descriptions are not correctly described in Appendix A of the *Sun Dual FastEthernet/SCSI 6U CompactPCI Adapter With PMC Installation and User's Guide* (806-6042).

TABLE 1 shows the correct pin descriptions for the Ethernet connectors.




FIGURE 2 Ethernet Connector Pins

TABLE 1 Pin Descriptions for the Two 8-Pin RJ-45 Connectors (Ports 0 to 1)

Description	Port 0	Port 1
TD+	1	1
TD-	2	2
RD+	3	3
Not Used	4	4
Not Used	5	5
RD-	6	6
Not Used	7	7
Not Used	8	8